

High power Negative No 3

D²

Date.	Turner's Name.	Consecutive Number.	Framer's Name.	R or A	Date.	Finisher's Name.	Edger's Name.	Out of Shop.
1895	Walker	530/1	Not packed	-		Godfrey	W766	June 1/95
June 1	"	145		-		"	"	29/95
" 29	"	631		-		"	"	March 9/95
" 1996	"	959		-		"	"	Aug 10/96
Mich 14	"			-		"	"	March 20/97
Aug 8	"	56520		-		"	"	Dec 18/97
1897	"	57639		-		"	"	Aug 10/98
Mich 19	"			-		"	"	Oct 25/98
Dec 17	"	58866		-		"	"	Oct 29/99
1898	"	59015		-		"	"	" 25/99
Aug 12	"			-		"	"	Nov 24/99
Oct 21	"			-		"	"	"
1899	"			-		"	"	Dec 12/99
Oct 20	Walker	60520		-		"	"	Nov 23/99
"	"	532		-		"	"	
"	"	7/48		-		"	"	
"	"	7/49		-		"	"	
"	"	814		-		"	"	
"	"	7/60		-		"	"	
"	"			-		"	"	
"	"	61123		-		"	"	
"	"	61643		-		"	"	
June 1	"	739		-		"	"	
22	Horton	599		-		"	"	
"	"	978		-		"	"	
"	"	62021		-		"	"	
"	"	62847		-		"	"	
May 1901	Walker	63179		-		"	"	
"	"	63697		-		"	"	
Nov 1/01	"	63969		-		"	"	
"	"	621430		-		"	"	
"	Walker	64808		-		"	"	
"	"	809		-		"	"	

Brent Archive ©2008

D²

1" x 2" M P Negative

C²

Date.	Turner's Name.	Consecutive Number.	Framer's Name.	R or A	Date.	Finisher's Name.	Edger's Name.	Out of Shop.
		61014				Huggin	Bomb	Jan 22/1900
		61085				"	"	Feb 27/1900
		61358				"	"	" -

Brent Archive ©2008